


Feed Master, Inc.


Installation Made Easy

Loom sizes from 3/8" thru 1 1/2"


Wires, cables and hoses and gages, up to 4 gage PowerAmp / Generator cable.




Place wire(s) through the side opening of the Feed Master tool and pivot so that wire(s) are running through the tool and past the handle.



Grip the handle and secure wire(s) with thumb.



Lightly grip split plastic tubing with opposite hand with the slit facing outwards.



Hold the tube in a stationary position and pull Feed Master through split tube with the other hand while keeping wire(s) in place with thumb.